

ZCZCDPG968

DAN: 464-011371

INPUT CDSN: DK1980

BFN: PA091512

TOR: 091759Z JAN 87

TUT: 091800Z JAN 87

ROUTING= DPG

WIRE SVC= **UNASSIGNED**

COMMDIS=**UNASSIGNED**

RTTUZYUJ RUEDGFA0057 0091513-UUUU--RUTLAAB.

ZNR UUUUU ZYN ZPD

R 091512Z JAN 87

FM FBIS PM

STAT

TO RUFLAAB/FBIS WASHINGTON DC

ACCT FBPA-EWDX

BT

UNCLAS

ATTN

STAT

ONLY FSB/FED

SUBJ

SERVICE: INTERNET EQUIPMENT WEEKLY REPORT

PA091512

INSPECTED THE INTERNET SHELTER ON A DAILY BASIS THIS WEEK BECAUSE OF THE AIR CONDITIONING CONTROL PROBLEM. THE CONTROLS HAVE WORKED ALL WEEK UNTIL THIS MORNING WHEN THE RELAY WAS STUCK AGAIN. HAVE NOTIFIED STS WHICH RELAY IS CAUSING THE PROBLEM SO THAT CAN BRING A REPLACEMENT WHEN THEY RETURN FOR MORE TESTING.

ANOTHER PROBLEM DEVELOPED DURING THE WEEK, THE UPS SYSTEM IS GIVING AN ALARM INTERMITTENTLY. THE MANUAL STATES THAT THE DISPLAY IS SUPPOSED TO INDICATE WHAT IS CAUSING THE ALARM BUT IT DOESN'T. IT COULD BE ANYTHING FROM INPUT OVER OR UNDER VOLTAGE TO INTERNAL COOLING FANS NOT OPERATING PROPERLY. WHATEVER IT IS, THE ALARM CONDITION IS MINOR BECAUSE MAJOR ALARMS ARE STORED IN MEMORY AND THIS ONE IS NOT. SINCE IT IS APPARENTLY MINOR AND OCCURS ONLY OCCASIONALLY I DON'T BELIEVE IT IS A SERIOUS PROBLEM. HAVE NOTIFIED STS OF THE UPS ALARM PROBLEM ALSO. REGARDS. 09/1519Z JAN

STAT

BT

#0057

NNNN